



Câmera Axis M1054  
 Sensor de presença  
 Cabo UTP instalado sob o alisar da porta por restaurador

Para infraestrutura subterrânea

Reviz	Revision note	Date	Signature	Checked

Item#	Quantity	Title/Name, designation, material, dimension etc	Article No./Reference

Designed by	Checked by	Approved by - date	Filename	Date	Scale
				00/00/00	

Edition	Sheet
0	1/1